

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7A




FIG. 7B

	I	II	III	IV	V	VI	VII	VIII
$V_{x1}$	H	H	H	H	L	L	L	L
$V_{x2}$	H	H	L	L	H	H	L	L
$V_{x3}$	H	L	H	L	H	L	H	L
$V_{g31}$	$V_{31}$	L	$V_{31}$	L	$V_{31}$	L	H	L
$V_{g32}$	$V_{32}$	$V_{32}$	L	L	H	H	L	L
$V_{g33}$	$V_{33}$	H	$V_{33}$	H	$V_{33}$	H	L	H

I : NORMAL OPERATION CONDITION

VIII : ABNORMAL CONDITION (SHUTDOWN)

FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12

